		1. DATE SUBMITTED 1 August 2000 Received 8/3/00						
This form is in three parts. Submitters must complete unshaded blocks in Part A and as much of Part B as possible. WSH will complete Part C (implementation details). If there is no specific required change date, enter 60 days from date submitted. Address questions to NWS Change Management at (301) 713-1373. Submit change requests to the NWSRC mailbox (External: NWSRC@noaa.gov).								
2. ORIGINATOR OFF	FICE 3. SUBM	MITTING AUTHORITY	4. COGNIZANT TEC	CHNICAL INDIVIDUAL	5. ORIGINATOR TRACKING NUMBER			
APO	Routing	Ward Seguin Code: W/APO1	Name: Woody Robert Routing Code:FSL/A Phone: : (303) 497- (301) 713-3409x110	APO	P431_FSL_A100082			
6. SYSTEMS AFFECT	TED BY CHANGE	☐ ATA PRODUCTS (C		rts Sunnlement)	7. WSH TRACKING NUMBER			
☐ ASOS	X AWIPS	_ `		HER (specify)	NWS 619			
8. TITLE OF CHANG								
	Radar prod	ducts not updating	on large display	pane	1			
9. TYPE OF CHANGE	E			10. SITES AFFECTED (Att	tach Part B, Page 2, if needed)			
□HARDWARE	☐ SOFTW	_	ENTATION ONLY	All sites				
	11. STATEMENT OF REQUIREMENT, PROBLEM, OR DEFICIENCY OF EXISTING SYSTEM (Include problem report reference numbers.) Radar data display times are not in agreement with radar menu "green" times. The forecaster must manually replenish the large pane to display current radar products.							
12. KNOWN OR PRO	POSED SOLUTION	N (Include source and des	scription of new featur	res or data products.)				
IGC_ Process cod	IGC_ Process code has been modified to correct the problem. See attachment A for installation instructions.							
13. ALTERNATE SOL	LUTIONS							
None								
14. REQUIRED CHANGE DATE	15. RATIONALE	e for required change	E DATE (Include propo	osed priority, if known.)				
ASAP	To provide current data to the forecasters.							
		CC	CB/PMC/CMB DE	CISION				
16. DECISION AUTH	IORITY LEVEL	☐ CCB LEVEL ONL	LY X FAST TR	ACK PMC or N\	WS CMB DECISION REQUIRED			
17. CCB LEVEL DEC	ISION	☐ APPROVED		SIGNATURE				
		☐ RECOMMEND	RECOMMEND APPROVAL		DATE SIGNED			
		☐ DISAPPROVE	ĒD	DATE SIGNED				
	FOR USE ONLY WHEN PMC or NWS CMB DECISION REQUIRED							
18. PMC OR NWS CMB DECISION		☐ APPROVED		SIGNATURE				
		☐ DISAPPROVE	.D	DATE SIGNED				

NWSRC Form 1001, 9/15/99

Part A - Page 1

1. ORIGINATOR TRACKING NUMBER **NWS CHANGE FORM** P431_FSL_A100082 PART B All RC/ECP submissions must also address the following information. Indicate if any areas are unknown or do not 2. WSH TRACKING NUMBER apply. State why information is unknown and when it will be available. Attach extra pages if necessary, referencing each applicable subject. NWS 619 FUNDING INFORMATION 3. SOURCE OF 4. TOTAL COST Estimate costs and indicate known sources of funding. (Include travel time, installation time, administrative **FUNDING** time, and software development time when applicable.) 5. DEVELOPMENT COSTS (Estimate development costs) AMOUNT Covered by the routine O&M costs. \$2000 6. OPERATIONAL TEST AND EVALUATION COSTS (Estimate test and evaluation costs) AMOUNT 7. PRODUCTION COSTS (Include acquisition, kit proofing, spares, delivery, and documentation costs) **AMOUNT** N/A 8. COMMUNICATIONS SERVICE/CIRCUITS COSTS (Include installation and recurring costs) **AMOUNT** AMOUNT 9. IMPLEMENTATION SUPPORT COSTS (Include travel, installation, and administrative costs) 9A. LIFE CYCLE SUPPORT COSTS (Less communications service/circuits) **AMOUNT** Ν/Δ SUPPORTING INFORMATION AND SCHEDULES Provide detailed information needed to implement the requested change. 10. DEVELOPMENT STATUS/SCHEDULE (Major milestones such as Start, Beta 11. PRODUCTION STATUS/SCHEDULE (Major milestones such as Test, and OT&E) Solicitation, Contract Start Date, Delivery Date, Kit Proofing, etc.) N/A N/A 12. IMPLEMENTATION/RETROFIT SCHEDULE 13. FACILITY INFORMATION (Attach facility drawings/plans.) N/A 14. COMMUNICATIONS INSTALLED (Type required, who will order, and 15. COMMUNICATIONS SERVICE/CIRCUITS TO BE REMOVED associated hardware required; attach Part B, Page 2, if needed.) 16. REQUIRED CLEARANCES, WAIVERS, AND LICENSES (Include person or 17. COORDINATION OF CHANGE WITH OTHER CHANGES organization responsible for obtaining each) The patch is intended for R4.3.1 sites. 18. PHYSICAL ITEMS AND DOCUMENTS AFFECTED (Include part, serial, and 19. STAFF RESOURCE IMPACTS (Skills and workload impact on document numbers. Attach Part B, Page 2, if needed.) maintainers, operators, and managers.) 20. LOGISTICS IMPACTS (Include facilities, maintenance, training, and support 21. OPERATIONAL IMPACTS (Include continuity and back up needs equipment impacts.) and plans.) 22. ADDITIONAL MAJOR CHANGE ACTIVITIES (Include who will accomplish each of them and staff hours required.) Tested on NMTW and RNK.

NWS CHANGE FORM PART B - PHYSICAL ITEM AND DOCUMENT IMPACT MATRIX SUPPLEMENT This information is required prior to publication of Engineering Modification Notes and Software Release Notes. List physical items to be replaced and specify any changes in related documentation. (Submitters should complete this information, if known. WSH will assist.)					1. ORIGINATOR TRACKING NUMBER P431_FSL_A100082 2. WSH TRACKING NUMBER NWS 619					
										3. ITEM NAME, CIRCUIT TYPE,
SOFTWARE VERSION, OR SITE LOCATION	REPLACE MODIFY	A. PART NUMBER OR CONFIGURATION	B. SERIAL NUMBER(S) OR COMMENTS	CONFIGURATION		A. IDENTIFIER	B. REV	A. IDENTIFIER	B. REV	
N/A										
				+	 					
	+		 	+	+	 		 		
	-	 	 	+	+	-	 	 '	+	
	+	 	 	+	+	 	 '	 '	+	
	<u> </u>	<u> </u>	<u> </u>		 	<u> </u> '	 '	<u> </u>	 	
	'					,	'	<u> </u>		
_	Ţ '			7		· '		\[\]		
						,				
				1			<u> </u>			
					1					
					1					

NWSRC Form 1001, 9/15/99

Part B - Page 2 (Physical Item and Document Impact Matrix Supplement)

NWS CHANGE FORM PART C		P431_FSL_A100082			
WSH is responsible for Part C, but submitters may complete sections that would help clarequirement or the necessary implementation actions.	arify the change	2. WSH TRACKING NUMBER NWS 619			
3. CCB COST EVALUATION		<u>'</u>			
NWS COST \$ FAA COST \$ DOD COST \$ OTHER AGENCY COST \$ TOTAL COST \$ (SPECIFY)					
4. IMPLEMENTATION DOCUMENTS REQUIRED					
☐ Engineering Modification Note ☐ Software Release Notes ☐ Other Document (Specify)					
ADDITIONAL IMPLEMENTATION INSTRUCTIONS (e.g., Implementation schedule, parts shipping instructions, equipment disposal procedures, additional documentation required, and status reporting instructions.) Include documentation, data input, notification vehicle, or specific action step required to verify completion of the implementation activity.					
5. IMPLEMENTATION ACTIVITY REQUIRED	6. REQUIRED COMPLETION DATE	7. RESPONSIBLE PERSON AND OFFICE	8. DOCUMENT OR ACTION REQUIRED TO VERIFY COMPLETION		
1. SST will place the software patch on the systems of the affected sites.	TBD	Thigpen/SST W/APO3	N/A		
2. Ensure this change is reported to the Weather Service Headquarters (WSH) through the Engineering Management Reporting System (EMRS) according to the instructions in Engineering Hanbook number 4, part 2. Record this RC number (NWS 619) in Block 17a of the EMRS report.	TBD	ESA at each site listed in Part A-10 (Sites Affected)			
3. Ensure the appropriate WSH management information systems and configuration management data bases are updated to reflect these changes	TBD	Michelle deTommaso W/OSO113			

NWSRC Form 1001, 9/15/99

Part C - Page 1

Attachment A

Installation Instructions

Log out of the workstation
Place the IGC_Process file on each workstation in /awips/fxa/bin
Log back in and restart D2D